AGENDA

UNSAFE STRUCTURES BOARD CITY COMMISSION MEETING ROOM - CITY HALL MAY 19, 2005 3:00 P.M.

RETURN HEARING (OLD BUSINESS)

CASE NO: CE03121109

CASE ADDR: 1115 NW 3 AV
OWNER: MORGAN, GENE & CINDY EDWARDS VICE

INSPECTOR: ROBERT A PIGNATARO

VIOLATIONS: FBC 111.1.1

THE C.B.S. REAR STRUCTURE AND WOODEN STORAGE SHED HAVE DETERIORATED FROM THE ELEMENTS AND HAVE NOT BEEN MAINTAINED ACCORDING TO THE REQUIREMENTS OF THE FLORIDA BUILDING CODE OR THE MINIMUM HOUSING CODE OF THE CITY OF FORT LAUDERDALE.

FBC 111.2.1.1.1

THE BUILDING IS VACANT AT THIS TIME.

FBC 111.2.1.2.1

THE FASCIA, SOFFIT AND CEILING IS FALLING DUE TO EXPOSURE TO THE ELEMENTS.

FBC 111.2.1.2.2

THE ROOF, ROOF STRUCTURE, CEILING, THE DOORS AND WINDOWS, ARE ALL PARTIALLY DESTROYED DUE TO THE EXPOSURE TO THE ELEMENTS AND NOT BEING MAINTAINED PROPERLY.

FBC 111.2.1.2.4

THERE ARE SETTLEMENT CRACKS AROUND THE CONCRETE BLOCK STRUCTURE.

FBC 111.2.1.2.5

THE ELECTRICAL IS PARTIALLY DESTROYED DUE TO THE EXPOSURE TO THE ELEMENTS.

FBC 111.2.1.2.6

THERE ARE SEVERAL PILES OF DOG FECES ON THE FLOOR AND THE WASTE SYSTEM IS NOT WORKING, CAUSING AN UNSANITARY CONDITION.

FBC 111.2.2.1

THE COST TO ALTER OR REPAIR THE BUILDING EXCEEDS 50% OF THE VALUE OF THE BUILDING.

FBC 111.2.2.2

THE COST OF THE STRUCTURAL REPAIRS EXCEEDS 33% OF THE VALUE OF THE BUILDING.

AGENDA

UNSAFE STRUCTURES BOARD CITY COMMISSION MEETING ROOM - CITY HALL

MAY 19, 2005 3:00 P.M.

RETURN HEARING (OLD BUSINESS)

CASE NO: CE03051368 CASE ADDR: 1225 NW 16 ST

OWNER: FLETCHER-ALLEN, SHIRLEY M, VERNON C. HILLS, DELBERT HILLS, JAMES HILLS

OWNER: FLETCHER-ALLE INSPECTOR: WAYNE STRAWN

VIOLATIONS: FBC 111.1.1

THE RESIDENTIAL SINGLE STORY CONCRETE MASONRY STRUCTURE HAS DETERIORATED FROM THE ELEMENTS AND HAS NOT BEEN MAINTAINED ACCORDING TO THE REQUIREMENTS OF THE FLORIDA BUILDING CODE OR THE MINIMUM HOUSING CODE OF THE CITY OF FORT LAUDERDALE.

FBC 111.2.1.2.2

THE STRUCTURE IS UNIFORMLY DESTROYED DUE TO TERMITE AND WATER DAMAGE. SOME OF THE STRUCTURAL ROOF TRUSSES AND JOISTS ARE DETERIORATED AND ROTTED.

FBC 111.2.1.2.3

THE ROOF SHEATHING HAS DETERIORATED AND IS MISSING IN AREAS.

FBC 111.2.2.1

THE COST TO ALTER OR REPAIR THE BUILDING EXCEEDS 50% OF THE VALUE OF THE BUILDING.

FBC 111.2.2.2

THE COST OF THE STRUCTURAL REPAIRS EXCEEDS 33% OF THE VALUE OF THE BUILDING.